

SUPPORTED HOUSING ACCOMMODATION

THE WAYRE
ROSEMARY CLOSE
High Street, Old Harlow
Essex, CM17 0DS

FIRE RISK ASSESSMENT

General Statement	<u>Page</u>
INDEX	2
General Statement	3
Evacuation Procedure – Appendix A General Information	7
Evacuation Procedure – Appendix B Evacuation Procedure & Instructions	8
Evacuation Procedure – Appendix C Evacuation Team & Responsibilities	9
Fire Safety Action Plan	10

Person With Fire Safety Responsibility

Overall Responsibility Andrew Murray - Head Of Service Tel Number: 01279 446676

Fire Safety Coordination Viv Hales – Supported Housing Manager Tel Number: 01279 446317

Fire Safety Support – Health & Safety Team Natasha Terrell – Human Resources / Health & Safety Manager

Tel: 01279 446022

Jackie Davies - Health & Safety Officer

Tel: 01279 446499

FIRE RISK ASSESSMENT

SUPPORTED ACCOMMODATION

THE WAYRE & ROSEMARY CLOSE

General Statement

The Regulatory Reform (Fire Safety) Order 2005 places statutory duties on employers to implement procedures with regards fire safety at places of work.

In order to help ensure the safety of staff and to comply with current legislation, should a fire occur at The Wayre, a well-documented safety plan is essential.

It should include a general assessment of the main hazards and details of the control measures put in place to minimise risk in the event of a fire.

The appendices, attached to the fire risk assessment, provide additional information and advice on general evacuation procedures and duties undertaken by specific members of staff and volunteers.

There is an Action Plan within the Fire Safety document; this is in place for either immediate action, planned action or for active monitoring to take place.

Additional information to the Plan is a Proforma for the scheme which gives locations of utilities and useful premise information.

Failure to comply with the fire risk assessment will be considered a breach of Harlow Council's health and safety procedures and could result in disciplinary action being taken.

The Wayre complex operates a NO SMOKING policy in all communal areas.

Fire Prevention

The Wayre is a residential, listed building, within the grounds there are 12 one bed bungalows that are used as supported accommodation. There are a further 12 one bed bungalows opposite the main house (Rosemary Close).

The Wayre has a common room, communal laundry with washers and drier and there is a kitchen off the laundry. The common room has two large doors which can be locked and bolted. There is an electric fire set into the common room/lounge but it is never used.

There is a communal garden to the rear of the property. There are two stairwells and one lift and a reasonably large basement.

Rosemary Close bungalows are individual properties located across the road from The Wayre. Each has its own front door access and garden. The supported housing scheme consists of 12 one bed bungalows and 1 two bed bungalow. The tenants use the facilities based at the The Wayre.

Within the Wayre building the main fire risks are; electricity, rubbish, heating, storage of flammable materials. The elderly or disabled, who may require wheelchair access, also reflects the type of evacuation that takes place.

The communal areas and each individual property has a pull cord system linked through to the Call Handling Service Provider, which has a guaranteed 24 hour 365 day response.

As part of a planned system upgrade all smoke detectors have been replaced in 2011.

There is a key safe facility on all schemes which allows access to tenants properties by emergency services only.

A fire log book is kept in the alarm cupboard of each scheme which records the weekly tests and check dates of the fire panel.

a) **Electricity**

All electrical equipment and appliances should be listed for regular PAT testing which is scheduled periodically by the Health & Safety Team.

Any obvious faults with electrical equipment or systems, including lighting and wiring, should be reported to HTS (Property & Environment) Ltd immediately.

b) Rubbish

Every effort must be made to ensure that unwanted materials and rubbish are removed from the complex, in particular the laundry, and disposed of as quickly as possible.

There are weekly refuse collections from the building and fortnightly collections of recycled waste.

c) <u>Heating</u>

The building heating system is regularly serviced to ensure that it is safe and does not pose a fire risk.

The gas supply system is checked on an annual basis by a Gas Safe registered contractor, HTS (Property & Environment) Ltd.

There is district heating on site where the boiler feeds the properties and communal rooms.

d) Flammable Liquids/Substances

There is the use of cleaning liquids and powders, dry goods and cloth materials/toilet rolls, which are stored safely, in very small quantities and kept to a minimum.

Flammable materials should not be stored near to where work is carried out that might cause a fire risk.

All liquids are stored appropriately and stored in their correct containers and disposed of in the correct manner.

Evacuation

If there is an evacuation situation out of hours, the Call Handling Service Provider will contact the on call service provider between the hours 5.00pm-12 midnight Mon-Fri and 8.30am to 12 midnight Weekends and Bank Holidays. Outside of these hours HTS (Property & Environment) Ltd would be contacted.

During working hours, if the Supported Housing Officer is not on site, they would be made aware of the situation.

THE FIRE BRIGADE HAVE ADVISED THAT TENANTS SHOULD REMAIN IN THEIR INDIVIDUAL PROPERTIES UNLESS THEY ARE IN THE IMMEDIATE LOCATION OF THE FIRE, IN WHICH CASE THEY SHOULD MAKE THEIR WAY TO A PLACE OF SAFETY

On the arrival of the fire brigade they will determine: When and if to commence a full evacuation When to instigate a visual inspection When tenants can return to their premises When to involve the Police Any other steps appropriate to the circumstances

Fire Precautions

In order to minimise the risk from any fire that may occur within The Wayre complex, and to ensure safe evacuation, the following control measures have been implemented.

a) Evacuation Routes

To ensure safe evacuation the routes must be kept free of flammable materials and obstructions at all times.

b) Fire Exits

All appropriate fire exits must be unlocked when the building is in use.

They must be kept free of all obstructions, both inside and out, and be available for use when required.

c) Fire Doors

Fire doors are provided to help prevent the spread of smoke and fire and must be kept closed.

d) Fire Extinguishers

Fire extinguishers are positioned in appropriate locations of the complex.

Extinguishers must not be removed from their designated location. The extinguishers are maintained and tested yearly.

Staff should familiarise themselves with the location and operation of extinguishers, and the types of fire they are suitable for. There is a fire blanket in the kitchen.

e) Fire Alarm

The Wayre is fitted with two separate fire alarm systems, the smoke detectors in tenants properties are linked to the emergency alarm system and are tested 6 monthly by the Supported Housing Officers. The Call Handling Service Provider provides maintenance of this system on a 24-hour 365-day basis.

The fire alarm panel in common areas is tested weekly by the Supported Housing Officers; a different call point will be used to activate the alarm every time it is tested.

Faults are reported to Central Control for any necessary repairs.

Staff should familiarise themselves with the location of the call points within their work areas.

f) Fire Drills

Tenants will be advised of any changes to fire procedures as and if necessary.

g) Signs

Appropriate fire safety signage is displayed throughout the building indicating the fire exit/s and action notice information.

People with Disabilities

Supported Housing Officer, in liaison with the fire brigade, if appropriate, may assist the less able tenants off the complex if and where necessary.

Training

Regular fire safety updates are provided as part of Harlow Council's commitment to Health and Safety related training.

General

Although every effort will be made to ensure that fire safety standards are maintained within the Wayre Supported Housing complex, this can only effectively be achieved with the cooperation of staff and tenants.

Deficiencies with any of the fire precautions should initially be referred to the Supported Housing Manager.

The fire risk assessment, and appendices, will be reviewed on a periodic basis.

Health & Safety Team September 2018

SUPPORTED ACCOMMODATION

THE WAYRE

FIRE RISK ASSESSMENT - Appendix A

EVACUATION PROCEDURE

GENERAL INFORMATION

- 1. Whenever there is a continuous operation of the fire alarm the fire procedure must be instigated. The only exception to this being when the alarm is tested weekly and the alarm will be operated as a continuous sound.
- 2. If appropriate use the evacuation route nearest to your location if a full evacuation is required.
- 3. Fire Action Notices and procedures are displayed throughout the building for visitors information and action.
- 4. Be aware of any staff or visitors who may require assistance during evacuation.
- 5. A member of staff, if on site, should make themselves aware and that they are acting as the responsible person for the evacuation prior to the Fire Brigade attending.
- 6. All persons must remain at the assembly point until formal permission to leave or re-enter the building has been given.
- 7. Please forward concerns or comments regarding any of the procedures to the Health & Safety Team or the Supported Housing Manager.

Health & Safety Team September 2018

SUPPORTED ACCOMMODATION

THE WAYRE

FIRE RISK ASSESSMENT - Appendix B

EVACUATION PROCEDURE & INSTRUCTIONS

ON DISCOVERY OR SUSPICION OF A FIRE (REGARDLESS OF HOW SMALL)

- 1. Raise the alarm by breaking the nearest call point
- 2. Call the Fire Brigade (see below for further details)
- 3. Warn people in the vicinity of the fire if possible
- 4. Commence evacuation procedures if necessary

ON HEARING THE ALARM

- 5. Treat every fire alarm operation as if it were a fire
- 6. If possible, close doors and window to help prevent the spread of smoke and fire
- 7. Walk to the nearest safe exit and proceed to the assembly point if evacuating
- 8. The Supported Housing Officer, if on site/call handling provider will ensure that the Fire Brigade has been called.

ASSEMBLY POINT – THE WAYRE - FRONT OF CAR PARK
ROSEMARY CLOSE - GREEN TO SIDE OF BUNGLAOWS

CALLING THE FIRE BRIGADE

- 9. Call the Fire Brigade immediately to every fire or on suspicion of a fire
- 10. Lift the receiver and dial 999
- 11. When the operator answers ask for Fire and you will be connected to the Fire Brigade
- 12. When the Fire Brigade operator answers give the location as:

THE WAYRE / ROSEMARY CLOSE, HIGH STREET, OLD HARLOW, ESSEX, CM17 ODS

Do not replace the receiver until the address has been correctly repeated back to you

Health & Safety Team September 2018

SUPPORTED ACCOMMODATION

THE WAYRE & ROSEMARY CLOSE

FIRE RISK ASSESSMENT - Appendix C

EVACUATION TEAM - EVACUATION TEAM RESPONSIBILITIES

Supported Housing Manager - Viv Hales 01279 446317

GREEN TEAM – OFFICE TELEPHONE NUMBER 01279 446177

Joanne Delahunt	Supported Housing Officer	07764 927307
Maggie Nudd	Supported Housing Officer	07764 927312
Tracy Ostacchini	Supported Housing Officer	07764 927308 (p/t)
Holly Shoard	Supported Housing Officer	07720 468869
Claire Yeo	Supported Housing Officer	07764 927299
Karen Sheppard	Supported Housing Officer	07764 927303

SUPPORTED HOUSING TEAM LEADERS

Tracy Quley	01279 446345
Debbie England (interim)	01279 446169
Pool Phones	07855 954143

- Overall responsibility for the evacuation process if on site/if evacuation is required
- Will ensure Fire Brigade has been called
- Liaise with emergency services
- Ensure tenants are at the assembly point if evacuation has taken place
- Do not re-enter the building complex until advised to do so

Health & Safety Team September 2018

FIRE RISK ASSESSMENT SUPPORTED ACCOMMODATION

THE WAYRE & ROSEMARY CLOSE

ACTION PLAN

	Hazard & Potential Risk	Who Is At Risk	Action Required	By Who	Timescales & Review
Fire exit routes could be compromised due to layout of furniture in the common rooms Some doors leading out of the Some series Key Holders / Police Other Agencies Meeting), held twice yearly in every scheme September 20 Ensure users of the common room keep fire exits assessable, if furniture is Tenants and other users of the kept of meeting.	Evacuation Routes Supported Housing Schemes — clarity required confirming the positioning of furniture in common room areas and the use of doors as fire exits Fire exit routes could be compromised due to layout of furniture in the common rooms Some doors leading out of the common rooms (not marked as fire exits), are locked — not push pad emergency — tenants unaware of procedures in using these doors hindering an evacuation — fire/doors should not be propped open to avoid	Council Employees Visiting Tenants Key Holders / Police Other Agencies Utility Officers	reminded, periodically, of the fire procedures and the importance of keeping all access routes clear and free of obstructions / furniture To be raised as a set item on the agenda for the TPM, (Tenant Participation Meeting), held twice yearly in every scheme Ensure users of the common room keep fire exits assessable, if furniture is moved then it must be replaced to original position afterwards Ensure any alternative doors have keys in them for use in an emergency – when the room is in use ensure unlocked to aid a quicker exit – ensure locked when	Tenants and other users of the common room Tenants and other users of the	Twice yearly in each scheme commencing September 2017 Records to be kept of meetings within each

Hazard & Potential Risk	Who Is At Risk	Action Required	By Who	Timescales & Review
Signage				
Check signage to exit routes are clear and up to date Ensure adequate signage in common room for fire procedures/exit locations and Action Notices Confirm assembly point has been agreed and tenants are aware of location - Tenants could be misguided in a possible evacuation	Tenants Council Employees Visiting Tenants Key Holders / Police Other Agencies Utility Officers Maintenance Staff	External Contractor visits yearly to service and maintain the fire extinguishers on site – a review of current fire safety signage will be carried out on these visits at each scheme Appropriate action will be taken and necessary signage displayed as and if required	Anglia Fire Contractor Communicating with Health & Safety / Supported Housing Officers	To commence signage reviews whilst on extinguisher inspections - from November 2011 – yearly in each scheme
Fire Alarm				
Fire alarm system on site is checked by the Supported Housing Officers weekly and noted in fire alarm log book Alarms should receive a full service and be on a regular maintenance programme to ensure efficiency and reliability in the event of activation in a fire	Tenants Council Employees Visiting Tenants Key Holders / Police Other Agencies Utility Officers Maintenance Staff	Confirmation that an external Contractor visits 6 monthly to inspect, service and maintain the fire alarm systems on each scheme – information recorded and logged in fire book	HTS (Property & Environment) Ltd	Ongoing 6 monthly inspections – Nov 2011

Additional Information	Who Is At Risk	Action Required	By Who	Timescales & Review
Health & Safety Checklist				
All Supported Housing Officers carry out a Health & Safety checklist consisting of general repair inspections, lighting, fire extinguisher checks, access routes, exits/fire doors, signage, alarm tests and ensuring Fire Plans are displayed			Supported Housing Officers	Weekly
Lounge chairs in the landing & stairwell have additional cushions. Extra coverings could act as a potential flammable fire hazard – trip hazard causing an obstruction		Additional, furnishings not approved have now been removed	Supported Housing Officer & Tenants	Ongoing inspections – (Dec 2011 onwards)
No visible fire extinguishers in the Common Room. If someone felt competent to put out a small, non threatening fire, there would be no fire extinguisher in the room to use in a fire		Possible installation of suitable extinguisher if necessary – extinguisher in hallway which may deem to be adequate. External Contractor visits to service fire extinguishers on site – a review of current fire safety equipment is carried out periodically		From November 2011 – yearly in each scheme

Additional Information			
New blinds have recently been installed to the windows in all of the common rooms. The fire exit doors have also been fitted with blinds to aid security of the building	The blinds MUST be pulled open and secured back when the room is in use. The fire exit door must not be compromised in any way due to the blinds/cords obstructing the use of the door in an emergency evacuation situation. The door should be easy to access and cause no difficulty for users with walking aids, wheelchairs or scooters		From January 2012
	The exit signage must be clearly visible, and the PUSH BAR accessible at all times To be raised as a set item on the agenda for the TPM, (Tenant Participation Meeting), held twice yearly in every scheme	Supported Housing Officers	Twice yearly in each scheme commencing September 2017 Records to be kept of meetings within each scheme