The Manager Tesco Supermarket Church Langley Harlow, Essex. CM17 9TE

Environmental Health

Harlow Council Civic Centre The Water Gardens Harlow Essex CM20 1WG www.harlow.gov.uk

Our Ref: 014/DT/03104

Your Ref:

Date: 15th May 2014

Tesco Filling Station, Church Langley Way, Harlow, Essex. CM17 9TE

Dear Sir or Madam

Please find enclosed an inspection report for the above installation.

Please do not hesitate to contact me should you wish to discuss this matter.

Yours faithfully

David Taylor

Senior Environmental Health Officer Tel: 01279 446105 Fax: 01279 446639 david.taylor@harlow.gov.uk

Copy: Tesco head office via email admin.petroleum@uktesco.com

Harlow District Council Civic Centre The Water Gardens Harlow Essex. CM20 1WG



LA-PPC Inspection Report

General Information

General Information		
Inspection Type	Compliance	
Local Authority	Harlow District Council	
Site Name and Address	Tesco Filling Station, Church Langley Way, Harlow, Essex. CM17 9TE	
Installation Type	Filling Station	
Permit Reference	PPC1/1.4/TESCO A2.1/98	
Site Representative Seen	Stella Martin	
Regulator/representative	Harlow Council: David Taylor	
Inspection Date	31 st March 2014	
Report Date	15 th May 2014	
Duration of Inspection	<1 hour	
Review of permit conditions undertaken	New revised permit to be issued before January 2015	

Recent History

	Comments	Action
Number of complaints received	None	None
Process/Installation changes	Harlow Council was notified that the pumps and stage II vapour recovery equipment were to be replaced during 2014. A number of documents have been lodged with the council including certificate of conformity for the proposed stage II system. The information also covers staff training, loading and discharging procedures, schedule or preventative maintenance and, pro-forma record sheets.	Please see notes below.

Future Developments

Tuture Developments	Comments	Action	
Information relating to EPR	New Process Guidance issued 12/2013	For information	
	LAPPC Risk Method March 2009 updated July 2013		

Other relevant information	None	None
----------------------------	------	------

Risk Assessment

Risk Assessment Score	5
Summary of changes	None

Summary of Inspection

Satisfactorily managed installation but certain records could not be located.

Actions Required

Actions required	
Reference to any breach of condition (or not) and other compliance issues as necessary	The stage II VR certificate appears' to relate to the installation before the pumps and VP II were replaced during August 2013. I should be grateful if you would provide a commissioning certificate for the new installation.
Tiecessai y	Certain maintenance and check records (on the forms provided by Tesco in April 2013) could not be found at the time of my visit. I regret that my visit was unannounced and therefore it is likely that these checks are being undertaken but the records were not immediately available. I should be grateful if you would clarify what periodic checks are made by staff and how these are recorded. I am aware that the site relies on DCD but I am unclear on the extent of training undertaken by PFS staff and no records could be located.
Other relevant information	None

Compliance Checking

Inspection List	√, × or N/A	Condition of observation details	Action Required			
Logbook and Records						
Storage tank summary	✓	1 and 4 Diesel	None			
		2, 3, 5,and 6 unleaded				
Records of uncontrolled leaks	✓	None	None			
Stage I vapour recovery test certificate	✓	27 th November 2013	None			
Stage II vapour recovery	✓	19 th October 2011				
PVRV checks	✓	27 th November 2013	None			
Competent person(s)	✓	No information available				
Copy of permit	✓	On site	None			
Maintenance records/schedule	✓	Provided April 2013	None			
Notifications received by the regulator of accidents, breakdowns or emissions likely to affect the local community during the period under review.	✓	None	None			

Site inspection				
Condition of filling connection point seals	✓	Not examined in detail		
Connection points secure?	✓	Yes	None	
Different vapour and filling fittings?	✓	Yes	None	
Signs correct, clear and clean?	✓	Yes	None	
Condition of manholes	✓	Not inspected	None	
General Housekeeping	✓	Satisfactory	None	

1 - Compliance Assessment

- Compilance Assessment		
Scoring for Compliance Assessment		
Scale of Non-Compliance	Possible Score	Score Awarded
(A) Incident leading to justified complaint but no breach of any specific permit condition or of the general/residual BAT condition.	0 points	0
(B) Incident leading to a justified complaint*.	5 points per incident	0
(C) Breach of permit not leading to formal action.	10 points per breach	0
(D) Incident leading to formal caution, Enforcement Notice or prosecution.	15 points per incident	0
(E) Incident leading to a Prohibition Notice or Suspension Notice.	20 points per incident	0
	Total (Max. 50):	0

2 - Assessment of Monitoring, Maintenance and Records

		Possible Score		
Criterion	Yes	No	N/A	Score Awarded
(A) Are emissions and emissions monitoring recorded as required in the permit?	0	10	0	0
(B) Process operation modified where any problems indicated by monitoring?	0	5	0	0
(C) Has a written maintenance programme for pollution control equipment been provided to the regulator?	0	5	0	0
(D) Is there a log book at the permitted premises incorporating details of all maintenance, examination and testing, inventory checking, installation and repair work carried out?	0	5	0	0
(E) All relevant documents forwarded to the authority by date required?	-5	10	0	0
			Total:	0

3 - Assessment of Management, Training and Responsibility

coring for Assessment of Management, Training and Responsibility	Pos	ssible So	ore	Score
Criterion	Yes	No	N/A	Awarded
(A) Are procedures in place to ensure proper management, supervision and training for process operations, proper use of equipment and effective preventative maintenance on all plant and equipment concerned with the control of emissions to the air?	0	5	0	0
(B) Are all staff with responsibility for operating the installation trained to be aware of their responsibilities under the permit?	0	5	0	5
(C) Does the operator maintain, and make available on request, a statement of training requirements for each operational post?	0	5	0	0
(D) Does the operator keep, and make available, a record of the training received by each person whose actions may have an impact on the environment?	0	5	0	0
(E) Is there a competent trained person who remains near the tanker during unloading? (Delivery drivers may be trained as the competent person.)	0	5	0	0
(F) Is an 'appropriate' environmental management system in place and working effectively?	-5	0	0	0
			Total:	5

4 - Determination of Regulatory Effort from Scores

Actual score = 5	Score band = <30	Category = Low
-------------------------	------------------	-----------------------