

The Manager
Tesco Stores Limited
Church Langley Way
Harlow
Essex
CM17 9TE

## **Environmental Health**

Harlow Council Civic Centre The Water Gardens Harlow Essex CM20 1WG www.harlow.gov.uk

Our Ref: PPCIVA/16/02237

Your Ref:

Date: 29/04/2016

## Environmental Permitting (England and Wales) Regulations 2010 Tesco Church Langley Filling Service Station

Dear Sir or Madam

As part of our inspection programme I wish to confirm my visit of the 28<sup>th</sup> April 2016, to the above premises.

I would like to take this opportunity to thank Lynsey Doyle for her assistance during the inspection.

Please find enclosed an inspection report for the above installation.

Please do not hesitate to contact me should you wish to discuss this matter further.

Yours sincerely

Steven Adams

Senior Environmental Health Officer

Tel: 01279 446105 Fax: 01279 446639

Steven.adams@harlow.gov.uk

Email copy: admin.petroleum@uktesco.com

Harlow District Council Civic Centre The Water Gardens Harlow Essex. CM20 1WG



## **LA-PPC Inspection Report**

**General Information** 

General information	
Inspection Type	Compliance
Local Authority	Harlow District Council
Site Name and Address	Tesco Filling Station, Church Langley Way, Harlow, Essex. CM17 9TE
Installation Type	Filling Station
Permit Reference	PPC1/1.4/TESCO A2.1/98
Site Representative Seen	Lynsey Doyle
Regulator/representative	Harlow Council: Steven Adams
Inspection Date	28 <sup>th</sup> April 2016
Report Date	29 <sup>th</sup> April 2016
Duration of Inspection	30
Review of permit conditions undertaken	Revised permit issued in 2015

**Recent History** 

	Comments	Action
Number of justified complaints received	None	None
Process/Installation changes	None	None

**Future Developments** 

Comments		Action
Information relating to EPR	Current Guidance issued 12/2013 LAPPC Risk Method updated July 2013	For information
Other relevant information	None	None

Diel	, A.	~~	 	ant

111011 7 10000011101111	
Risk Assessment Score	Low

Summary of changes	None
<u> </u>	1

## Summary of Inspection

None

**Actions Required** 

Reference to any breach of condition (or not) and other compliance issues as necessary	6. The petrol vapour capture efficiency shall be tested and the results recorded at least once every three years by checking that the vapour/petrol ratio under simulated petrol flow conditions, or by any other appropriate methodology.
Other relevant information	None

Compliance Checking					
Inspection List	√,×or N/A	Condition/observation details	Action Required		
Logbook and Records					
Incident Log book present? Any incidents of vapour leaks? Any incidents of vapour locks?	✓	No reported incidents	None		
Is the certification for the servicing of the Stage I vapour recovery system present on site?	✓	02/02/2016	None		
Is the certification for the servicing of the Stage II vapour recovery system present on site? Hydrocarbon capture not less than 85%	×	Certificate dated 16/04/2013  Effectiveness of the vapour recovery system must be tested at least once every three years.	The effectiveness of the vapour recovery system should be tested for effectiveness and a copy of the certificate sent to this office.		
Petrol delivery and vapour recovery systems for vehicle petrol tanks shall be tested in accordance with manufacturer's specifications.	<b>√</b>	02/02/2016	None		
Has the vapour containment integrity been tested?					
Has the effectiveness of the vapour recovery system been tested?					
Is the certification for the servicing of the pressure relief valves (PVRV) present on site?	<b>√</b>	02/02/2016	None		
Are there training details for staff and competence records?	<b>✓</b>	Bronze training covers the permit condition and vapour recovery. All kiosk staff trained up to date.	None		
	<u></u>	<u> </u>	<del></del>		

Is there a convert the normit on site?		Yes	None	
Is there a copy of the permit on site?	✓	169	INOHE	
Maintenance records/schedule	1	All records up to date and stored in the log book.	None	
Notifications received by the regulator of accidents, breakdowns or emissions likely to affect the local community during the period under review.	<b>√</b>	None received	None	
Site inspection				
Storage tank summary	<b>√</b>	<ol> <li>Diesel</li> <li>Unleaded</li> <li>Super unleaded</li> <li>Diesel</li> <li>Unleaded</li> <li>Super unleaded</li> <li>Super unleaded</li> </ol>	None	
Are connection points on tank filling pipes and vapour return pipes fitted with secure seals?	<b>√</b>	Not examined in detail	None	
Condition of filling connection points	×	There is a heavy build up of oil deposits and oil soaked rags indicating regular minor spills in the vicinity of the connection points at the time of delivery.  Petrol sludge contains a corrosive acid which can damage the filling connection points and the surrounding area over time.  Please investi cause of these spillages and to prevent or spills and at the least ensure spill kits are an all drivers.  Please carry of clean of this a remove oil slu		
Are the fittings for delivery and vapour return pipes different?	<b>✓</b>	Yes	None	
Vent pipes are clearly labelled, securely supported and protected?	✓	Yes None		
Is there written procedures for the delivery and filling of tanks?	×	The current procedure for leak free delivery and spillage clean up are not being followed	Please ensure all delivery drivers are fully instructed on the company's load and discharge procedures.	

		and the second s	
Are connections for vapour return and delivery hose clearly locked and labelled?	✓	Yes	None
ls there clear notices/signage near the vapour return connection point reading:			
" connect vapour return line before off- loading"			
"the maximum number of tanker compartments which can be discharged"			
Condition of manholes	×	Turn lock missing on a manhole cover allowing the entry of water.	Replace missing lock.
General Housekeeping	×	The area around the delivery filling points is covered in petrol sludge and discarded rags letting down an otherwise well managed site.	Please carry out a deep clean of this area to remove oil sludge and contaminated rags.

END

1 - Compliance Assessment

Scoring for C	Compliance Assessment		
Scale of N	on-Compliance	Possible Score	Score Awarded
	nt leading to justified complaint but no breach of any specific permit on or of the general/residual BAT condition.	0 points	0
	it leading to a justified complaint*.	5 points per incident	0
(C) Breach	of permit not leading to formal action.	10 points per breach	10
(D) Incider	nt leading to formal caution, Enforcement Notice or prosecution.	15 points per incident	0
(E) Incider	nt leading to a Prohibition Notice or Suspension Notice.	20 points per incident	0
		Total (Max. 50):	10

2 - Assessment of Monitoring, Maintenance and Records

Scoring for Assessment of Monitoring, Maintenance and Records				
Criterion		ssible Sc	Score	
		No	N/A	Awarded
(A) Are emissions and emissions monitoring recorded as required in the permit?	0	10	0	10
(B) Process operation modified where any problems indicated by monitoring?	0	5	0	0
(C) Has a written maintenance programme for pollution control equipment been provided to the regulator?	0	5	0	0
(D) Is there a log book at the permitted premises incorporating details of all maintenance, examination and testing, inventory checking, installation and repair work carried out?	0	5	0	0
(E) All relevant documents forwarded to the authority by date required?	-5	10	0	0
			Total:	10

3 - Assessment of Management, Training and Responsibility

Scoring for Assessment of Management, Training and Responsibility						
	Possible Score		ore	Score		
Criterion	Yes	No	N/A	Awarded		
(A) Are procedures in place to ensure proper management, supervision and training for process operations, proper use of equipment and effective preventative maintenance on all plant and equipment concerned with the control of emissions to the air?	0	5	0	5		
(B) Are all staff with responsibility for operating the installation trained to be aware of their responsibilities under the permit?	0	10	0	0		
(C) Does the operator maintain, and make available on request, a statement of training requirements for each operational post?	0	5	0	0		
(D) Does the operator keep, and make available, a record of the training received by each person whose actions may have an impact on the environment?	0	5	0	0		
(E) Is there a competent trained person who remains near the tanker during unloading? (Delivery drivers may be trained as the competent person.)	0	5	0	0		
(F) Is an 'appropriate' environmental management system in place and working effectively?	-5	0	0	0		
			Total:	5		

4 - Determination of Regulatory Effort from Scores

Actual score = <b>25</b>	Score band = <30	Category = <b>Low</b>