Mr S R Chandrakumar S R Services 153 Lonsdale Road Enfield Middlesex EN2 7NB

#### **Environmental Health**

Harlow Council Civic Centre The Water Gardens Harlow Essex CM20 1WG www.harlow.gov.uk

Our Ref: 14/DT/04091

Your Ref:

Date: 8<sup>th</sup> April 2014

# **Environmental Permitting (England and Wales) Regulations 2010 Texaco Filling Station, Elizabeth Way, Harlow, Essex. CM19 5AR**

Dear Sir

Please find enclosed an inspection report for the above installation.

Please do not hesitate to contact me should you wish to discuss this matter.

Yours faithfully

**David Taylor** 

Senior Environmental Health Officer Tel: 01279 446105 Fax: 01279 446639 david.taylor@harlow.gov.uk Harlow District Council Civic Centre The Water Gardens Harlow Essex. CM20 1WG



## **LA-PPC Inspection Report**

#### **General Information**

Inspection Type	Compliance		
Local Authority	Harlow District Council		
Site Name and Address	Texaco Service Station, The Pinnacles, Harlow, Essex. CM19 5AR		
Installation Type	Loading and offloading of petroleum		
Permit Reference	EPR/b/1/14 SR Services		
Site Representative Seen	S R Chandrakumar		
Regulator/representative	Harlow Council: David Taylor		
Inspection Date	31 <sup>st</sup> March 2014		
Report Date	7 <sup>th</sup> April 2014		
Duration of Inspection	<1 hour		
Review of permit conditions undertaken	A review of permit conditions will be undertaken during 2014 following publication of the new process guidance note.		

**Recent History** 

	Comments	Action
Number of complaints received	None	None
Process/Installation changes	None	None

**Future Developments** 

	Comments	Action
Information relating to EPR	New Process Guidance issued 12/2013 LAPPC Risk Method March 2009 updated July 2013	For information
Other relevant information	None	None

#### **Risk Assessment**

Risk Assessment Score	20

Summary of changes	None
--------------------	------

### **Summary of Inspection**

Training records out of date. No maintenance procedure available

**Actions Required** 

Reference to any breach of condition (or not) and other compliance issues as necessary	See below
Other relevant information	

**Compliance Checking** 

Inspection List	√, × or N/A	Condition/observation details	Action Required		
Logbook and Records					
Storage tank summary	✓	Tanks 1 and 2 unleaded Tank 3 diesel	None		
Records of uncontrolled leaks	✓	None reported	None		
Stage I vapour recovery test certificate	✓	15 <sup>th</sup> March 2013	None		
Stage II vapour recovery	✓	N/A	None		
PVRV checks	✓	15 <sup>th</sup> March 2013	None		
Competent person(s)	<b>√</b>	3 persons trained but all certificates are out of date.	Ensure that all persons receive appropriate training and that this is regularly updated.		
Copy of permit	✓		None		
Maintenance records/schedule	<b>√</b>	No procedure available	Please provide a copy of your maintenance procedure for the maintenance of all tanks, dispensing equipment and valves used to prevent the escape of vapours		
Notifications received by the regulator of accidents, breakdowns or emissions likely to affect the local community during the period under review.	<b>√</b>	None	None		
Site inspection					
Condition of filling connection point	✓	Appear satisfactory	None		

seals			
Connection points secure?	✓	Yes	None
Different vapour and filling fittings?	✓	Yes	None
Signs correct, clear and clean?	✓	Yes	None
Condition of manholes	✓	Water logged	Reduce water levels
General Housekeeping	✓	Satisfactory	None

#### Risk Assessment – Texaco Service Station

April 2014

1 - Compliance Assessment

Scoring for Complia	nnce Assessment		
Scale of Non-Cor	npliance	Possible Score	Score Awarded
	g to justified complaint but no breach of any specific permit the general/residual BAT condition.	0 points	0
(B) Incident leading	g to a justified complaint*.	5 points per incident	0
(C) Breach of perr	nit not leading to formal action.	10 points per breach	0
(D) Incident leading	g to formal caution, Enforcement Notice or prosecution.	15 points per incident	0
(E) Incident leading	g to a Prohibition Notice or Suspension Notice.	20 points per incident	0
		Total (Max. 50):	0

2 - Assessment of Monitoring, Maintenance and Records

scoring for Assessment of Monitoring, Maintenance and Records		Possible Score		
Criterion	Yes	No	N/A	Score Awarded
(A) Are emissions and emissions monitoring recorded as required in the permit?	0	10	0	0
(B) Process operation modified where any problems indicated by monitoring?	0	5	0	0
(C) Has a written maintenance programme for pollution control equipment been provided to the regulator?	0	5	0	5
(D) Is there a log book at the permitted premises incorporating details of all maintenance, examination and testing, inventory checking, installation and repair work carried out?	0	5	0	0
(E) All relevant documents forwarded to the authority by date required?	-5	10	0	0
			Total:	5

3 - Assessment of Management, Training and Responsibility

		Possible Score		
Criterion	Yes	No	N/A	Awarded
(A) Are procedures in place to ensure proper management, supervision and training for process operations, proper use of equipment and effective preventative maintenance on all plant and equipment concerned with the control of emissions to the air?	0	5	0	5
(B) Are all staff with responsibility for operating the installation trained to be aware of their responsibilities under the permit?	0	5	0	5
(C) Does the operator maintain, and make available on request, a statement of training requirements for each operational post?	0	5	0	5
(D) Does the operator keep, and make available, a record of the training received by each person whose actions may have an impact on the environment?	0	5	0	0
(E) Is there a competent trained person who remains near the tanker during unloading? (Delivery drivers may be trained as the competent person.)	0	5	0	0
(F) Is an 'appropriate' environmental management system in place and working effectively?	-5	0	0	0
			Total:	15

#### 4 - Determination of Regulatory Effort from Scores

Actual score = 20	Score band = <b>0 -30</b>	Category = <b>low</b>
-------------------	---------------------------	-----------------------